


INSTRUCTIONS, REFLECTIVE TAPE KIT (GPSLR)

KIT P/N 287962-01



CONSPICUITY TAPE, 3/4" WIDE X 92" LG.
P/N 287961-01
QTY. 2

1. Move the platform all the way out (**FIG. 1-1**). Refer to **GPSLR OPERATING INSTRUCTIONS** decal on vehicle and **GPSLR Operation Manual**.
2. Raise (UP) or lower (DOWN) the platform to a comfortable working height.




PLATFORM OUT
FIG. 1-1

⚠ WARNING


To prevent accidental personal injury and equipment damage, make sure power is disconnected from Liftgate while installing parts.

3. Disconnect power from Liftgate by disconnecting negative (-) battery cable from negative (-) battery terminal (**FIG. 1-2**).



DISCONNECTING POWER
FIG. 1-2


4. Prepare mounting surface (**FIG. 2-1**), for tape, with a general-purpose cleaning solution such as Simple Green. Ensure the cleaning solution will not leave a residue.



CLEANING THE TAPE MOUNTING SURFACE
FIG. 2-1


NOTE: Avoid touching the adhesive side of the tape to prevent contamination.

5. Peel backing from 1 strip of reflective (conspicuity) tape and apply it across the platform hinge, from RH side to LH side (**FIG. 2-2**). Use a clean cloth to press the tape firmly to the surface.



APPLYING THE TAPE TO PLATFORM HINGE
FIG. 2-2

6. Use a utility knife with a new blade to cut the tape at the grooves on each side of hinge links (**FIG. 3-1**).



CUTTING TAPE ON PLATFORM HINGES
FIG. 3-1

7. Remove tape, from the moving hinge links (**FIG. 3-1**), with long-nose pliers.


CAUTION

Avoid heating the tape too long so it doesn't melt.

8. To set each section of tape and remove wrinkles, use a heat gun about 1" from the tape (**FIG. 3-1**).


NOTE: Align the colors on the tape for flipover hinge with the colors on the tape for the platform hinge.

9. Peel backing from 1 strip of reflective (conspicuity) tape and apply it across the flipover hinge, from RH side to LH side (**FIG. 4-1**). Use a clean cloth to press the tape firmly to the surface.




APPLYING THE TAPE TO FLIPOVER HINGE
FIG. 4-1

10. Repeat steps 6 through 8 for flipover
(FIG. 5-1).




CUTTING TAPE ON FLIPOVER HINGES
FIG. 5-1

11. Remove nut from negative (-) battery terminal. Reconnect the negative (-) battery cable to negative (-) battery terminal (**FIG. 6-1**). Reinstall and tighten nut.



RECONNECTING POWER
FIG. 6-1

12. Stow the Lifgate and hook chain to lift arm, if equipped. (**FIG. 6-2**). Refer to **GPSLR OPERATING INSTRUCTIONS** decal on vehicle and **GPSLR Operation Manual**.



STOWED PLATFORM
FIG. 6-2