





MAXON Technical Bulletin: General Lubrication Advisory for Liftgates



Many MAXON® liftgates manufactured today are equipped with grease fittings located at critical rotational points and bearing surfaces. It's of critical importance that these grease points are lubricated at the prescribed intervals as outlined in our maintenance manuals.

Following the published maintenance guidelines on lubrication will ensure these critical components perform trouble free for many years. Failure to grease these critical areas of the liftgate at prescribed intervals will result in premature failure of components and result in unnecessary and avoidable downtime of equipment.